


Surface treatment

Different types of surface treatment for our straps are shown below:
From left to right; bluing, yellow, black, silver, orange, and galvalume.

Surface finish appearance	Surface finish name	Remarks
	Blueing	Our proprietary heat treatment method that creates oxide film on strap surface to strengthen rust prevention and reduce shape defects. The strap surface is additionally wax-coated to further prevent rust. The wax coating also contributes to smooth tightening and improved work efficiency.
	White	A strap made by slitting a cold-rolled steel sheet into narrow bands with a specified width. The strap surface is wax-coated after evaporating oil on the surface.
	Color	A strap with coating treatment. Basic color is black but also comes in orange, silver and yellow (for lashing).
	Galvalume	A strap with zinc plating